

gauge conversion chart

Gauge to millimetre conversion chart

Gauge	Conversion to mm
25g	.50
24g	.60
22g	.70
20g	.90
18g	1.20
16g	1.60
14g	2.00
12g	2.80
10g	3.00
3/16	5.00
1/4	6.00